246 South Eighth Street (House) Philadelphia Philadelphia County Pennsylvania

1ABS PA 51- PHILA 665-

PHOTOGRAPHS

WRITTEN HISTORICAL AND DESCRIPTIVE DATA

HISTORIC AMERICAN BUILDINGS SURVEY
MID-ATLANTIC REGION NATIONAL PARK SERVICE
DEPARTMENT OF THE INTERIOR
PHILADELPHIA, PENNSYLVANIA 19106


Form 10-920 (June 1983)


UNITED STATES DEPARTMENT OF THE INTERIOR NATIONAL PARK SERVICE


HARS


ARCHITECTURAL DATA FORM

STATE	COUNTY		TOWN OR V	ICIMITY	
Pennsylvania	1		ł	Philadelphia	
<u> </u>				HABS NO.	
HISTORIC NAME OF STRUCTURE (INCLUDE SOURCE FOR NAME)			PA-5206		
246 South Eighth Street (House)			IA-3200		
SECONDARY OR COMMON NAMES OF STRUCTURE					
None					
COMPLETE ADDRESS (DESCRIBE LOCATION FOR RURAL SITES)					
246 South Eighth Street					
DATE OF CONSTRUCTION (INCLUDE SO	ARCHITECT(S) (INCLUDE SOURCE)				
1840-41 (Insurance Survey)		Unknown, builder Alexander Henry			
SIGNIFICANCE (ARCHITECTURAL AND HISTORICAL, INCLUOE ORIGINAL USE OF STRUCTURE) This rowhouse is a non-contributing structure just within the boundary of the Society Hill Historic District. Research disclosed no historic significance. Any architectural significance has been compromised by alterations and deterioration.					
STYLE (IF APPROPRIATE) Vernacular					
MATERIAL OF CONSTRUCTION (INCLUDE STRUCTURAL SYSTEMS)					
Red brick bearing walls with wood frame floors and roof.					
SHAPE AND DIMENSIONS OF STRUCTURE (SKETCHEO FLOOR PLANS ON SEPARATE PAGES ARE ACCEPTABLE)					
Front and rear three story blocks, pitched roof, see sketch					
EXTERIOR FEATURES OF NOTE					
Square headed venetian doorway transom, pedimented dormer, plain wood cornice					
INTERIOR FEATURES OF NOTE (DESCRIBE FLOOR PLANS, IF NOT SKETCHED)					
Some original panelled wood doors and trim					
MAJOR ALTERATIONS AND ADDITIONS WITH DATES					
Victorian shopfront inserted before 1914, including second entrance door at street level					
PRESENT CONDITION AND USE Interior condition is poor, rear block structurally unsound, partial collapse occurred in 1983; present use, vacant.					
OTHER INFORMATION AS APPROPRIATE					
Building vacant for atleast s squatters.	six years, with	periodic habita	tion by va	andals and urban	
SOURCES OF INFORMATION (INCLUDING LISTING ON NATIONAL REGISTER, STATE REGISTERS, ETC.)					
Architectural Historian, Sarah Rose, 1982					
COMPILER AFFILIATION Cooper Pratt Vallhonrat Archi Corporation, Developer	tects, for St.	George Land Acc	uisition	DATE May 1, 1984	









4TH FLOOR PLAN